

Fire Risk Assessment

Address of property assessed: 173 Brambles Chine, Freshwater

Number of floors: 1

Number of rooms: 4

Construction: *Brick*

Assessor: David Rose

Date of assessment: 1st October 2023

Responsible person: David Rose

Fire hazards and controls

Are fixed electrical installations inspected and tested every 5 years?

No, new schedule to be created.

Are electrical appliances periodically inspected and tested?

Yes, all electrical appliances subject to annual PAT test

Is the use of trailing leads and adaptors avoided where possible?

N/a

Are gas appliances periodically inspected and tested every 12 months?

Yes, gas appliances are subjected to an annual inspection and test

Is smoking permitted on the premises?

No. No Smoking Sign displayed in bungalow

Are suitable arrangements in place for those who wish to smoke?

Yes. Smoking is permitted outside the bungalow

Are the premises adequately secured to prevent unauthorised access?

Yes

Are combustible materials, waste and refuse bins stored safely clear of the premises or in purpose-built compounds/rooms?

Yes, refuse bins are stored in a clearly marked area next to the site office

Are fixed heating systems subject to periodic maintenance?

Yes, the central heating boiler is subject to an annual inspection

Are portable heaters subject to periodic inspection and used safely?

N/a, there are no portable heaters in the bungalow

Are there adequate fire precautions in the use of open fires and log burners?

N/a, there are no open fires or log burners in the bungalow

Are adequate measures taken to prevent fires from cooking?

Yes

Are filters and ductwork subject to regular cleaning?
N/a
Is the standard of housekeeping adequate to avoid the accumulation of combustible materials and waste?
Yes, the bins are emptied between lets
Are combustible materials kept separate from ignition and heat sources?
Yes
ls it ensured that all contractors who undertake work on the premises are competent and qualified?
Yes
Are suitable measures in place to address the fire hazards associated with the use and storage of dangerous substances?
N/a
Are there any other significant fire hazards in the premises?
No

Fire protection measures

Are all escape routes kept clear of obstructions to enable people to escape safely? Yes Are all fire exits easily and immediately openable? No. Thumb turn lock to be added to the emergency door. Emergency window locks to be removed. Are distances of travel considered reasonable? Yes Do the walls and structures protecting the stairway and escape routes provide an adequate level of fire resistance? N/a Is the fire resistance of doors to stairways and escape routes considered adequate? N/a Where necessary, are doors fitted with suitable self-closing devices that close the doors effectively? N/a Are there adequate levels of artificial lighting provided in the escape routes? Yes Where necessary, has a reasonable standard of emergency escape lighting been provided? Yes, an emergency rechargeable torch is provided. Where necessary, is a reasonable standard of fire exit and fire safety signs provided? N/a

Are smoke and/or heat alarms/detectors provided and is the extent and coverage considered adequate?

Yes, there is a heat detector fitted in the living room and a smoke detector fitted in each bedroom. The detectors are wirelessly linked.

Is there a reasonable provision of firefighting equipment (fire extinguishers, fire blanket)?

Yes, there is a fire extinguisher and a fire blanket provided

Management of fire safety

Are procedures in the event of fire appropriate and documented?

Yes, a fire evacuation plan is provided

Is the information on fire safety and the action to take in the event of a fire given to guests?

Yes, the information is reviewed annually

Are any staff members given regular instruction and training on the action to take in the event of a fire?

N/a

Are frequent checks carried out to ensure exit routes are kept clear and fire exits remain easily openable?

Yes, the bungalow is cleaned between lettings

Are periodic checks carried out on fire doors to ensure they remain in good condition and close effectively?

N/a

Where fitted, are weekly testing and six-monthly servicing routines in place for the fire detection and alarm system?

N/a

In self-catering premises, are all smoke/heat alarms (or fire detection and alarm systems, where fitted) tested at every changeover?

No. New smoke/heat alarm testing regime to be introduced.

Where fitted, are monthly and annual testing routines in place for the emergency escape lighting?

N/a

Where provided are fire extinguishers subject to annual maintenance?

Yes, the fire extinguisher is inspected annually

Are records of testing and maintenance maintained?

Yes

Action plan

If any of the above boxes are ticked with a 'No', the deficiencies should be described below, along with proposed action for rectification.

ACTIONS TO BE UNDERTAKEN	
Electrical Installation Condition Report (EICR) required	15 th Feb 2024
Thumb turn lock to be fitted to escape door	15 th Feb 2024
Escape window locks to be removed	15 th Feb 2024
Smoke/heat alarm test at changeover to be introduced	15 th Feb 2024